

**Inspection Photos**  
**Location Name: Heston LD06-635 PAD**  
**Location ID: 440372**



**Photo 1 – Unused Walkover Stand**



**Photo 2 – Unused Chemical Container**



**Inspection Photos**  
**Location Name: Heston LD06-635 PAD**  
**Location ID: 440372**



**Photo 3 – LD06-620 Wellhead – PA – Cut and Capped.  
Unmarked Risers**



**Photo 4 – Wellhead Sign**



**Inspection Photos**  
**Location Name: Heston LD06-635 PAD**  
**Location ID: 440372**



**Photo 5 – LD06-625 Wellhead**



**Photo 6 – Wellhead Sign**



**Inspection Photos**  
**Location Name: Heston LD06-635 PAD**  
**Location ID: 440372**



**Photo 7 – LD06-630 Wellhead**



**Photo 8 – Wellhead Sign**





**Inspection Photos**  
**Location Name: Heston LD06-635 PAD**  
**Location ID: 440372**



**Photo 9 – Gas Lift Injection Meter Shed**