

Inspection Photos
Location Name: Ruebel ET AL 36-1
Location ID:




Pic 1 tanks



Pic 2 gas meter run not calibrated.



Inspection Photos
Location Name: Ruebel ET AL 36-1
Location ID:



Pic 3 wellhead stained soil next to wellhead needs to be removed.