

Inspection Photos

April 27, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 438248

Location Name: Diamond T Sheep 7-92 /1-26

Inspection Document #: 702800155

Moffat County, CO

NWNW Section 26 T7N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 1. Photo taken from the Location entrance shows an overview of the Location. Sign in front of tank battery has correct Operator information.



Photo 2. Photo taken from the Location entrance shows an overview of the Location. Photo also shows areas to the south and southwest of the wells not necessary for production which have not been reclaimed (in the left of the photo).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 3. Photo taken from the southeast of the pad shows areas to the south and southwest of the wells not necessary for production which have not been reclaimed.

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 4. Photo taken from the northwest of the Location shows an overview of the Location and northwestern interim area.

Inspection Photos

Location Name: Diamond T Sheep 7-92 /1-26

Location ID: 438248



Photo 5. Photo taken from the northwest of the Location shows bare, unprotected soils in the interim areas.



Photo 6. Photo taken from the north of the Location shows rill erosion occurring on bare soils of the interim areas. Photo also shows where surface roughening was improperly performed by tracking perpendicular to the slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos

Location Name: Diamond T Sheep 7-92 /1-26

Location ID: 438248



Photo 7. Photo taken from the north of the Location shows rill erosion occurring on bare soils of the interim areas.



Photo 8. Photo taken from the west of the Location shows rill erosion occurring on bare soils of the interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 9. Photo taken from the south of the Location shows unmaintained erosion control BMPs. Soil has broken through the straw wattle and is accumulating offsite in native rangeland adjacent to the Location.



Photo 10. Refer to Photo 9 comment. Red circle shows soils accumulating in, and degrading adjacent areas.

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 11. Photos taken from the southeast of the Location show wind eroded soil accumulating and smothering vegetation in native rangeland adjacent to the Location. Also note the stakes from the completely buried straw wattle (red arrow).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 12. Photos taken from the fill slope at the south of the Location shows wind erosion occurring on unprotected soils. Vegetation on the slope is sparse and dominated by annual undesirable plant species/weeds.



Inspection Photos

Location Name: Diamond T Sheep 7-92 /1-26

Location ID: 438248



Photo 13. Photo taken from the south of the Location shows fill slopes with annual undesirable plant species/weed debris and weed skeletons which will soon become debris.



Photo 14. Photo taken from the interim area shows germination of cheatgrass throughout the photo and Russian thistle (red circle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 15. Photo taken from the south of the Location shows the basal rosettes of scotch thistle, a CO List B noxious weed in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos

Location Name: Diamond T Sheep 7-92 /1-26

Location ID: 438248



Photo 16. Photo taken from cut slope to the north of the Location shows the slope is unstabilized. Wind erosion was occurring. Photo also shows the slope is colonized by cheatgrass a CO List C noxious weed.



Photo 17. Photo taken from cut slope to the east of the Location shows rill erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248




Photo 18. Photo taken from the tank battery shows tanks with incorrect Operator information (red circle); COGCC well file records show Operator as “SWN Production Company LLC #10396.” Photo also shows stained soils at the base of the tank (red arrow).



Photo 19. Photo shows a sign has been added to the well. The sign reads with correct Operator information.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos

Location Name: Diamond T Sheep 7-92 /1-26

Location ID: 438248



Photo 20. Photos show tanks where labeling has been applied. Photos also show wildlife protection equipment to prevent wildlife access to secondary containment is insufficient to prevent wildlife entry.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 21. Photos show examples of unused equipment. Photos also show wildlife protection equipment to prevent wildlife access to secondary containment is missing or insufficient.



Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 22. Photos show wildlife protection equipment to prevent wildlife access to secondary containment is missing or insufficient. No safety labeling applied identifying fluids within containers in both photos.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800155

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 23. Photos show unused equipment throughout the Location.

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 24. Photo shows stained soils within the compressor station secondary containment BMP.



Photo 25. Photo shows stained soils within the tank battery secondary containment BMP.

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 26. Photos shows stained soils and unused equipment throughout the compressor shed Located at the north of the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702800155

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 27. Photos shows unused equipment, tools etc. throughout the compressor shed Located at the north of the Location. Photo also shows wildlife protection equipment to prevent wildlife access to the fluid filled container is missing or insufficient. No safety labeling identifying the fluid.

Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 28. Photos show stained soils and unused equipment throughout the compressor shed Located at the north of the Location.



Inspection Photos
Location Name: Diamond T Sheep 7-92 /1-26
Location ID: 438248



Photo 29. Photo shows stained soils around well API # 05-081-07817



Photo 30. Photo shows an open pipe at well API # 05-081-07804.