

Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 1. Overview of north portion of location taken facing south.



Photo 2. Overview of south portion of location taken facing south.

Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 3. Example of 1 of 4 wellhead signs with Sandridge still listed as operator/emergency contact.



Photo 4. 2 crypto mining generators on left and 4 crypto mining server farms on right.

