

**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Photo #1 Tanks.**

**Photo #2 Separator.**

**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Photo #3 ECDs and Separator.**



**Photo #4 Plastic buckets in separator house.**

Inspection Photos  
Location Name: Ferguson 2-25  
Location ID: 319714



Photo #5 Plastic buckets in separator house.

Photo #6 produced water tank.

Inspection Photos  
Location Name: Ferguson 2-25  
Location ID: 319714



**Photo #7 gap under produced water tank.**

**Photo #8 Produced water pit.**

Inspection Photos  
Location Name: Ferguson 2-25  
Location ID: 319714



**Photo #9 Hydrocarbons present in produced water pit.**

**Photo #10 Pump Jack.**