

FORM
43Rev
05/21

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

10/05/2021

Document Number:

402831646

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith
Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820
Address: 1875 LAWRENCE ST STE 1150 Fax: ()
City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

Identification Information

API Number: 05 - - OGCC Facility ID: 263590 Initial Form 19 or 27 Document number:
Facility Name: CHERYL ONSITE Facility Number: 42-23 Facility Type: PIT
Location QtrQtr: SENE Section: 23 Township: 33S Range: 67W Meridian: 6
County: LAS ANIMAS Field Name: PURGATOIRE RIVER
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer
Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

Rule 909.J Inspection Information

Date the Pit was Inspected 09/07/2021

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 261498 Facility Name: CHERYL 42-23 Facility Type: Oil and Gas Well
Location: QtrQtr: SENE Sec: 23 Twp: 33S Range: 67W Meridian: 6
County Name: LAS ANIMAS Latitude: 37.157540 Longitude: -104.851220

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 91804 Document Name: Cheryl 42-23 File Name: 261498 - EDD1 - 06282021.xlsx
SampleType: Matrix:
Facility ID: 261498 Sample ID: 628485 Sample Name: Cheryl 42-23 Sample Date: 06/10/2021
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-149708-1

Batch ID: 91806 Document Name: Cheryl 42-23 File Name: 261498 - EDD2 - 07192021.xlsx

SampleType: Matrix:

Facility ID: 261498 Sample ID: 628487 Sample Name: Cheryl 42-23 Sample Date: 06/10/2021

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: Remediation Number: Complaint Number: NOAV Number:

Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-149708-1

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
261498	402831653	261498 - Report2 - 07192021.pdf	Analytical Laboratory Report	PDF
261498	402831650	261498 - Results1 - 06282021.pdf	Analytical Laboratory Report	PDF

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	A task has been opened for the Integrity Group to review the information provided by the operator.	05/05/2022
Total: 1 comment(s)		