

FORM
43Rev
05/21

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

10/05/2021

Document Number:

402832188

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith
Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820
Address: 1875 LAWRENCE ST STE 1150 Fax: ()
City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

Identification Information

API Number: 05 - - OGCC Facility ID: 262364 Initial Form 19 or 27 Document number:
Facility Name: RETRIEVER Facility Number: 24-20 Facility Type: PIT
Location QtrQtr: SWSW Section: 20 Township: 34S Range: 65W Meridian: 6
County: LAS ANIMAS Field Name: PURGATOIRE RIVER
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer
Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

Rule 909.J Inspection Information

Date the Pit was Inspected 05/17/2021

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 260973 Facility Name: RETRIEVER 24-20 Facility Type: Oil and Gas Well
Location: QtrQtr: SWSW Sec: 20 Twp: 34S Range: 65W Meridian: 6
County Name: LAS ANIMAS Latitude: 37.063670 Longitude: -104.699080

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 91836 Document Name: Retriever 24-20 File Name: 260973 - EDD1 - 08302021.xlsx
SampleType: Matrix:
Facility ID: 260973 Sample ID: 628519 Sample Name: Retriever 24-20 Sample Date: 08/11/2021
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-151791-1

Batch ID: 91837	Document Name: Retriever 24-20	File Name: 260973 - EDD2 - 09202021.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 260973	Sample ID: 628520	Sample Name: Retriever 24-20
Collection Point: WellHead	Matrix: WATER	Pre Post: Rule 909.j initial sample
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: TestAmerica Inc.
		NOAV Number: _____
		Lab Sample ID: 280-151791-1

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
260973	402832191	260973 - Report2 - 0919021.pdf	Analytical Laboratory Report	PDF
260973	402832190	260973 - Report1 - 08302021.pdf	Analytical Laboratory Report	PDF

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	05/09/2022
Total: 1 comment(s)		