

FORM
43Rev
05/21

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

10/14/2021

Document Number:

402842318

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith
Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820
Address: 1875 LAWRENCE ST STE 1150 Fax: ()
City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

Identification Information

API Number: 05 - - OGCC Facility ID: 119928 Initial Form 19 or 27 Document number: _____
Facility Name: Deer Facility Number: 23-17 PIT Facility Type: PIT
Location QtrQtr: NESW Section: 7 Township: 34S Range: 65W Meridian: 6
County: LAS ANIMAS Field Name: PURGATOIRE RIVER
Federal, Indian or State Lease Number: _____

Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer
Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

Rule 909.J Inspection Information

Date the Pit was Inspected 05/13/2021

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 217786 Facility Name: RITA 2 Facility Type: Oil and Gas Well
Location: QtrQtr: NESW Sec: 17 Twp: 34S Range: 65W Meridian: 6
County Name: LAS ANIMAS Latitude: 37.083290 Longitude: -104.698000

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 92034 Document Name: edd1 File Name: 217786 - EDD1 - 08302021.xlsx
SampleType: Matrix:
Facility ID: 217786 Sample ID: 628724 Sample Name: Deer 23-17 Sample Date: 07/26/2021
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-151177-1

Batch ID: 92035	Document Name: edd2	File Name: 217786 - EDD2 - 08302021.xlsx
SampleType:	Matrix:	
Facility ID: 217786	Sample ID: 628725	Sample Name: Deer 23-17
Collection Point: WellHead	Matrix: WATER	Pre Post: Rule 909.j initial sample
Project Number:	Remediation Number:	Complaint Number:
Inspection Number:	Spill Number:	Laboratory: TestAmerica Inc.
		NOAV Number:
		Lab Sample ID: 280-151177-1

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
217786	402842322	217786 - Report2 - 08302021.pdf	Analytical Laboratory Report	PDF
217786	402842319	217786 - Report1 - 08302021.pdf	Analytical Laboratory Report	PDF

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	05/09/2022
Total: 1 comment(s)		