

# Inspection Photos

API: 009-05157

Operator: PONCHO PRODUCTION COMPANY

Inspection Date: 5/6/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing southeast toward the abandoned well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022



## Inspection Photos



**Photo 2.** Facing southeast toward the location. There is a water well and stock tank at the location belonging to the landowner. The black two tanks shown were equipment from the well site which need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022

## Inspection Photos



**Photo 3.** There are two tanks, pipe riser, meter run, and cement debris that remain. All equipment should have been removed within 3 months of well abandonment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022



## Inspection Photos



**Photo 4.** There are two tanks, pipe riser, and meter run that remain. All equipment should have been removed within 3 months of well abandonment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022

## Inspection Photos



**Photo 5.** Facing northeast at the location. There are areas of the location with no vegetation growth which will need to be reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022



## Inspection Photos



**Photo 6.** There is a yellow tank that remains at the southwest side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022

## Inspection Photos



**Photo 7.** There are abandoned pipe risers that remain 400 ft. north of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022



## Inspection Photos



**Photo 8.** There are abandoned pipe risers that remain 700 ft. northwest of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05157 | Date: 5/6/2022