

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 1 – Heater Treater and Gas Meter



Photo 2 – Pumping Unit



Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 3 – Unused Belts



Photo 4 - Gas Engine



Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 5 – Stained Soil at Engine



Photo 6 – Exhaust – Stained Soil

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 7 – Stained Soil at Exhaust




Photo 8 – Wellhead – Unmarked Riser

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 9 – ECD and Flare



Photo 10 – Tank Battery – Capacity Labels Missing

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 11 – Tank Battery Sign