

Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 316060

Location Name: Wilson Creek Unit-62N94W /4NWSE

Inspection Document #: 702800172

Rio Blanco County, CO

NWSE Section 4 T2N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-62N94W /4NWSE

Location ID: 316060



Photo 1. Photo shows an overview of the eastern portion of the Location.



Photo 2. Photo shows an overview of the western portion of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800172

Inspection Photos
Location Name: Wilson Creek Unit-62N94W /4NWSE
Location ID: 316060



Photo 3. Photo shows the wind direction indicator in disrepair.



Inspection Photos

Location Name: Wilson Creek Unit-62N94W /4NWSE

Location ID: 316060



Photo 4. Photo shows bird protection devices are missing or insufficient on pipe equipment to the northwest of the Location.



Photo 5. Photo shows bird protection devices are missing or insufficient on pipe equipment to the northeast of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800172

Inspection Photos
Location Name: Wilson Creek Unit-62N94W /4NWSE
Location ID: 316060



Photo 6. Photo taken from the north of the Location shows BMPs to prevent wildlife entry to the methanol tank secondary containment are in disrepair.

Inspection Photos

Location Name: Wilson Creek Unit-62N94W /4NWSE

Location ID: 316060



Photo 7. Photo shows what appears to be a soil stockpile to the west of the Location.



Photo 8. Photo shows what appears to be a soil stockpile to the east of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800172