

Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 25, 2022

Location sign.





Apr 25, 2022 1:39:
+40.2123N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

**Tank battery where the
spill/release occurred looking
north.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Apr 25, 2022 1:39:
+40.2125N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

**Potentially impacted material
within and on the exterior of the
tank battery secondary
containment structure (southeast
corner).**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 25, 2022

**Potentially impacted material
within the tank battery secondary
containment structure.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 25, 2022

**Potentially impacted material
within the tank battery secondary
containment structure (southwest
corner).**

Apr 25, 2022 1:40:
+40.2125N -108.2



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 25, 2022

**Potentially impacted material
within the tank battery secondary
containment structure (western
half of the tank battery).**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

Potentially impacted material within the tank battery secondary containment structure (northwest corner).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

Potentially impacted material within and on the exterior of the tank battery secondary containment structure (northwest corner).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

Northeast corner of the tank battery secondary containment structure. Note the potential impacts on the exterior of the secondary containment structure where fluids had escaped and the residual impact ring on the northeast corner of the tank battery secondary containment structure.





Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

Northeast corner of the tank battery secondary containment structure. Note the potential impacts on the exterior of the secondary containment structure where fluids had escaped and the residual impact ring on the northeast corner of the tank battery secondary containment structure.





Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 25, 2022

Potential impacts around the pump building located north of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Apr 25, 2022 1:43:
+40.2127N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

Northeast corner of the Pine Ridge Federal C1-W location. Note the potential impacts and what appears to be storm water.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Apr 25, 2022 1:46:
+40.2125N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

Apparent pit on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Apr 25, 2022 1:49:
+40.2123N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 25, 2022

**Apparent groundwater well
discharging fluids into the apparent
pit on location.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Mislabeled tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources