

Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 315050

Location Name: Wilson Creek Unit-63N94W /34SWNE

Inspection Document #: 702800176

Rio Blanco County, CO

SWNE Section 34 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34SWNE

Location ID: 315050



Photo 1. Photo taken from the center of the Location shows an overview of the well area.



Photo 2. Photo taken from the west of the Location shows storage of unused equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800176