

Inspection Photos

Location Name: Richardson E 2, 067-06338

Location ID: 214734



IMG 01

Location sign with emergency contact



IMG 02

Site layout (1/2)

Inspection Photos
Location Name: Richardson E 2, 067-06338
Location ID: 214734



IMG 3
Site layout (2/2)



IMG 4
Tank stored on interim reclamation zone

Inspection Photos
Location Name: Richardson E 2, 067-06338
Location ID: 214734



IMG 05
Separator vent properly screened



IMG 06
Produced water tank sign is not visible

Inspection Photos
Location Name: Richardson E 2, 067-06338
Location ID: 214734



IMG 07
Wattles are deteriorating and have become debris.



IMG 08
Access road culvert is filled with material

Inspection Photos
Location Name: Richardson E 2, 067-06338
Location ID: 214734



IMG 09

Cement debris near sound panels