

Inspection Photos
Operator: Hilcorp
API: 067-09460
Date: 5/5/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of kochia and mustard debris within the eastern project area.



Photo 4. View of the reference area comprised of cultivated wheat field and pinyon and juniper woodland with sagebrush, squirreltail, prickly pear, and yucca in the understory.