

# Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314513

Location Name: Wilson Creek Unit-63N94W /34NWNE

Inspection Document #: 702800181

Rio Blanco County, CO

NWNE Section 34 T3N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NWNE

Location ID: 314513



5/6/22  
+40.191468,-107.924630  
36° NE

**Photo 1.** Photo taken from the center of the Location shows an overview of the northern portion of the Location.



5/6/22  
+40.191496,-107.924748  
167° S

**Photo 2.** Photo taken from the center of the Location shows an overview of the southern portion of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800181

Inspection Photos  
Location Name: Wilson Creek Unit-63N94W /34NWNE  
Location ID: 314513



**Photo 3.** Photo shows a secondary containment BMP filled with fluid. Wildlife protection BMPs to enable wildlife egress are missing or insufficient.



## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NWNE

Location ID: 314513



**Photo 4.** Photo taken from the west of the Location shows a straw wattle not in proper functioning condition. Erosion is occurring throughout the slope at the western perimeter of the Location. Sediment leaving the Location appears to be causing degradation to areas offsite.



**Photo 5.** Refer to Photo 4 comments.

## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NWN

Location ID: 314513



**Photo 6.** Photo taken from the west of the Location shows gully erosion.



**Photo 7.** Photo taken from the west of the Location shows gully erosion. Photo also shows buried pipe which will need to be removed during reclamation.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800181