

Inspection Photos

API: 009-06570

Operator: ENERGY ALLIANCE COMPANY

Inspection Date: 5/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06570 | Date: 5/6/2022

Inspection Photos



Photo 1. All equipment and debris is removed. No crop has been planted this season.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06570 | Date: 5/6/2022