

Inspection Photos

May 6, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314510

Location Name: Wilson Creek Unit-63N94W /34NENW

Inspection Document #: 702800180

Rio Blanco County, CO

NENW Section 34 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NENW

Location ID: 314510



Photo 1. Photo taken from the southwest of the Location shows an overview of the Location.



Photo 2. Photo taken from the northeast of the Location shows the excavated well. A strong hydrocarbon odor was present. Photos also shows the sides of the pit may be too steep to allow wildlife escape and fencing to prevent access does not completely enclose the excavated area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800180

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NENW

Location ID: 314510



Photo 3. Photo taken from the northeast of the Location shows a pile of material excavated from around the well. BMPs to prevent the E&P waste from migrating off the Location were not present.



Photo 4. Photo taken from the area of the excavated well shows stained soils around the well. A strong hydrocarbon odor was present at the time of this inspection.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800180

Inspection Photos
Location Name: Wilson Creek Unit-63N94W /34NENW
Location ID: 314510



Photo 5. Photo taken from the northwest of the Location shows a flowline which will need to be removed during final reclamation.



Photo 6. Photo taken from the northwest of the Location shows a flowline (arrow) and pad (circle) which will need to be removed during final reclamation.

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NENW

Location ID: 314510



Photo 7. Photo taken from the northwest of the Location shows a straw wattle, which is presently in proper functioning condition to manage stormwater on the Location.



Photo 8. Photos shows power lines being decommissioned at the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800180