

Final Reclamation Inspection

March 8, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 332740

Inspection Document #: 697503922

Weld County, CO

SWSE Section 7 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: KAMMERZELL #7-44
Location ID: 332740



Photo 1. Photo taken from the location, facing West. Photo illustrates the location is dominated by annual, weedy vegetation (cheatgrass and Kochia). It appears as if there has been a significant amount of mulch applied throughout the location.



Inspection Photos
Location Name: KAMMERZELL #7-44
Location ID: 332740



Photo 2. Reference photo taken south and adjacent to the location, facing West. The common grass species observed were Smooth brome, Orchard grass and Canada wildrye.

