

Final Reclamation Inspection

May 6, 2022

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 332712

Inspection Document #: 697503928

Weld County, CO

SWSW Section 7 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SCHNEIDER 13-7-35
Location ID: 332712



Photo 1. Photo taken west of the well location, facing East. Photo illustrates only one well has been drilled at the location.

