

# Inspection Photos

STATE 36-05 BIG PIT

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/11/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 1.** Facing south at the beginning of the access road. Vegetation has not established along the former road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 2.** There is an erosion channel along the former road. This needs to be repaired and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 3.** Facing south toward the Big Pit location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 4.** Center of the Big Pit location. There are noxious weeds (Scotch thistle) beginning to grow that will need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 5.** East side of the location facing south. Some areas of the location have not establish sufficient vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 5/11/2022

## Inspection Photos



**Photo 6.** Drone aerial photo facing northeast toward the Big Pit location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 5/11/2022