

Inspection Photos
Location Name: State 26-2
Location ID: 327091



Photo 1 – Pumping Unit



Photo 2 – Exhaust removed

Inspection Photos
Location Name: State 26-2
Location ID: 327091



Photo 3 – Stained Soil



Photo 4 – Separator

Inspection Photos
Location Name: State 26-2
Location ID: 327091



Photo 5 – Unmarked Riser



Photo 6 – Gas Meter House

Inspection Photos

Location Name: State 26-2

Location ID: 327091




Photo 7 – Gas Meter Calibration Card



Photo 8 – Tank Battery

Inspection Photos
Location Name: Rothe 12-14-9-61
Location ID: 424216



Photo 9 – Tank Battery Sign



Photo 10 – Content and Capacity no longer visible