

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1SESE

Location ID: 334948



Photo #6687 from entrance to location.



Photo #6688 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1SESE

Location ID: 334948



Photo #6689 Wellhead sign weathered and not legible.

