

Inspection Photos

API: 073-06747

Operator: GRAND MESA OPERATING

Inspection Date: 5/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022

Inspection Photos



Photo 1. Facing toward the access point off of the County Road. There is gravel that remains that needs to be removed and regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022

Inspection Photos



Photo 2. Facing east toward the fenced location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022

Inspection Photos



Photo 3. Facing south toward the southwest portion of the location. This area shown in the photo is mostly undesirable weeds (*Kochia* sp.). This area needs to be reseeded and weeds controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022

Inspection Photos



Photo 4. View of groundcover shows mostly undesirable weeds (*Kochia* sp.) observed in the southwest portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022

Inspection Photos



Photo 5. Center of the location facing north. The desirable vegetation appears to be progressing in other areas of the location but has not reached 80% cover..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022

Inspection Photos



Photo 6. Center of the location facing west. The desirable vegetation appears to be progressing in other areas of the location but has not reached 80% cover..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022

Inspection Photos



Photo 7. Center of the location facing south. The desirable vegetation appears to be progressing in other areas of the location but has not reached 80% cover..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022

Inspection Photos



Photo 8. Center of the location facing east. The desirable vegetation appears to be progressing in other areas of the location but has not reached 80% cover..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06747 | Date: 5/16/2022