

Inspection Photos
Location Name: Fischer Mark Federal B1, 067-07073
Location ID: 215468



IMG 01
Location Sign



IMG 02
Site Overview

Inspection Photos
Location Name: Fischer Mark Federal B1, 067-07073
Location ID: 215468



IMG 03
Rip Rap



IMG 04
Waddles

Inspection Photos
Location Name: Fischer Mark Federal B1, 067-07073
Location ID: 215468



IMG 05
Perimeter ditch



IMG 06
Rip Rap

Inspection Photos
Location Name: Fischer Mark Federal B1, 067-07073
Location ID: 215468



IMG 07
Debris



IMG 08
Telemetry

Inspection Photos

Location Name: Fischer Mark Federal B1, 067-07073

Location ID: 215468



IMG 09
Valve cluster pit



IMG 10
Produced water tank hatch. Circled area is location to secure with pin or lock to further deter wildlife entry. In addition, tank paint has deteriorated

Inspection Photos
Location Name: Fischer Mark Federal B1, 067-07073
Location ID: 215468



IMG 11
Pump control panel



IMG 12
1" flow line to pump jack generator

Inspection Photos

Location Name: Fischer Mark Federal B1, 067-07073

Location ID: 215468



IMG 13

Separator vent stack screen



IMG 14

Produced water tank metal berm not painted uniformly

Inspection Photos
Location Name: Fischer Mark Federal B1, 067-07073
Location ID: 215468



IMG 15
Produced water tank sign



IMG 16
Pump jack and wellhead

Inspection Photos

Location Name: Fischer Mark Federal B1, 067-07073

Location ID: 215468



IMG 17

Access road culvert



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources