

Inspection Photos
Location Name: Hott 20-2 1, 067-06629
Location ID: 215024



IMG 01
Location Sign



IMG 02
Site Overview



Inspection Photos
Location Name: Hott 20-2 1, 067-06629
Location ID: 215024



IMG 03
Site overview



IMG 04
Produced water tank

Inspection Photos
Location Name: Hott 20-2 1, 067-06629
Location ID: 215024



IMG 05
Rip Rap



IMG 06
Rip Rap

Inspection Photos
Location Name: Hott 20-2 1, 067-06629
Location ID: 215024



IMG 07
Ditch



IMG 08
PA well

Inspection Photos
Location Name: Hott 20-2 1, 067-06629
Location ID: 215024



IMG 09
PA well with valve



IMG 10
Separator vent stack with screen



Inspection Photos
Location Name: Hott 20-2 1, 067-06629
Location ID: 215024



IMG 11
Wellhead with BOP