

Final Reclamation Inspection

May 11, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 329652

Inspection Document #: 697503946

Weld County, CO

NWSW Section 3 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CANNON RED W #3-12
Location ID: 329652



05.11.2022 13:01

Photo 1. Photo taken from the eastern well location, facing West. Photo illustrates Operator has performed final reclamation activities; however, the entire location has established with mostly Russian thistle. The fence around the location appears to be catching Russian thistle which is then depositing its seeds onto location.

Inspection Photos
Location Name: CANNON RED W #3-12
Location ID: 329652



Photo 2. Photo taken from the central well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CANNON RED W #3-12
Location ID: 329652



Photo 3. Reference photo taken from the well location, facing East. Photo illustrates sand sage and there is an understory of native grass species.



Photo 4. Photo taken from the associated offsite tank battery location, facing North. Photo illustrates the tank battery is still active for other nearby wells.