

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403051183

Receive Date:

Report taken by:

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

### OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	<b>Phone Numbers</b>
Address: <u>1775 SHERMAN STREET - STE 3000</u>		Phone: <u>(970) 313-5582</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80203</u>
Contact Person: <u>Jason Davidson</u>	Email: <u>jason.davidson@pdce.com</u>	Mobile: <u>( )</u>

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 9466 Initial Form 27 Document #: 200438847

#### PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☐ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: \_\_\_\_\_

#### SITE INFORMATION

No Multiple Facilities

Facility Type: <u>PIT</u>	Facility ID: <u>104726</u>	API #: _____	County Name: <u>ADAMS</u>
Facility Name: <u>CHAMPLIN 67 "F"</u>		Latitude: <u>39.866301</u>	Longitude: <u>-104.451354</u>
		** correct Lat/Long if needed: Latitude: <u>39.866301</u>	Longitude: <u>-104.451354</u>
QtrQtr: <u>NWNW</u>	Sec: <u>21</u>	Twp: <u>2S</u>	Range: <u>63W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

#### SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Agricultural (cultivated and pasture)

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

#### Other Potential Receptors within 1/4 mile

The Champlin 67F former location is surrounded by cultivated fields and pastureland in all directions. There is one mapped ephemeral stream and associated wetland located approximately 720 feet west. Depth to ground water is unknown, however, borings advanced in November 2016 to 9 feet did not encounter ground water. Based on the Division of Water Resources, Groundwater Levels in the Lost Creek Designated Groundwater Basin paper published in 2020, it is anticipated that the depth to water will be approximately 80 feet. However, a water well 2,340 feet southeast of the facility had a static water level of 120 feet in 1980 when it was drilled. There are no sensitive areas or wildlife habitats identified within a quarter mile of the former location.

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

- ☒ E&P Waste      ☐ Other E&P Waste      ☐ Non-E&P Waste
- ☒ Produced Water      ☐ Workover Fluids
- ☒ Oil      ☐ Tank Bottoms
- ☒ Condensate      ☐ Pigging Waste
- ☐ Drilling Fluids      ☐ Rig Wash
- ☐ Drill Cuttings      ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA) \_\_\_\_\_

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	Orgs- 12x12x10, Inorgs- 60x58x3	Subsurface Investigation Activities

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

The equipment has been removed from the Champlin 67F site. A site investigation conducted in 2016 indicated the presence of soil impacts greater than the COGCC Table 910-1 standards beneath the former produced water pit to a depth of approximately 5 feet but no contamination was present at a depth of 9 feet.

PDC will conduct site investigation activities, field screening, and confirmation sampling activities during closure in accordance with COGCC 900 Series Rules. Discrete soil samples will be collected and analyzed pursuant to Rule 915, following the general sample collection guidance in Rule 915.e.(2).

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Please refer to the attached Fremont Environmental Site Investigation Report for a summary of the proposed soil sampling activities at the Site.

#### Proposed Groundwater Sampling

- ☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

#### Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 62

Number of soil samples exceeding 915-1 45

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 3480

### NA / ND

-- Highest concentration of TPH (mg/kg) 5136

-- Highest concentration of SAR 82.9

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 10

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 1

Number of groundwater monitoring wells installed 1

Number of groundwater samples exceeding 915-1 1

NA Highest concentration of Benzene (µg/l) 1

NA Highest concentration of Toluene (µg/l) 1

NA Highest concentration of Ethylbenzene (µg/l) 1

NA Highest concentration of Xylene (µg/l) 1

NA Highest concentration of Methane (mg/l) 1

### Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

Please refer to the attached Fremont Environmental Site Investigation Report for a summary of the background samples collected at the Site.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 1

Volume of liquid waste (barrels) 1

☐ Is further site investigation required?

## REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Please refer to the attached Fremont Environmental Site Investigation Report for a summary of the proposed source removal activities. A total of approximately 65 cubic yards of petroleum impacted soil and approximately 375 cubic yards of material with elevated SAR and/or pH levels are proposed to be excavated for offsite disposal. All waste generated during the excavation activities will be managed and disposed of at a licensed disposal facility in accordance with Rules 905 and 906.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Please refer to the attached Fremont Environmental Site Investigation Report for a summary of the proposed remediation activities.

## Soil Remediation Summary

☐ In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

☐ Ex Situ

\_\_\_\_\_ Excavate and offsite disposal  
\_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_  
\_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ No Land Treatment  
\_\_\_\_\_ No Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ No Chemical oxidation  
\_\_\_\_\_ No Other \_\_\_\_\_

### **Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during site investigation activities.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

**Approved Reporting Schedule:**

☒ Quarterly

☐ Semi-Annually

☐ Annually

☐ Other

☐ **Request Alternative Reporting Schedule:**

☐ Semi-Annually

☐ Annually

☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

**Report Type:**

☐ Groundwater Monitoring

☐ Land Treatment Progress Report

☐ O&M Report

☒ Other Excavation/Remediation Report

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation?

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards?

Is additional groundwater monitoring to be conducted?

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

# RECLAMATION PLAN

## RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

SAR and/or pH impacts greater than the COGCC Table 915-1 limits will remain in place, including the background soil, at a depth greater than three feet. The surrounding cultivated area has historically been used for dryland wheat farming and is anticipated to remain in this use. Following remediation activities, PDC will develop a reclamation plan in accordance with the COGCC Rule 915.b. Operator Guidance Document, updated on March 11, 2022. The reclamation plan will be attached to a follow-up Form 27 Supplemental.

Is the described reclamation complete? No \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

## SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

## PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

## SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 11/01/2016

Proposed site investigation commencement. 10/31/2021

Proposed completion of site investigation. 02/22/2022

## REMEDIAL ACTION DATES

Proposed start date of Remediation. 07/25/2022

Proposed date of completion of Remediation. 07/29/2022

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

**OPERATOR COMMENT**

Location ownership transferred to PDC effective May 6, 2022.

PDC plans to submit a Supplemental Form 27 within 90 days of completing the proposed excavation activities.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jason Davidson

Title: Senior Env. Specialist

Submit Date:

Email: jason.davidson@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:

Date:

Remediation Project Number: 9466

**COA Type****Description**

--	--

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

403053582	SITE INVESTIGATION REPORT
-----------	---------------------------

Total Attach: 1 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)