

# Inspection Photos

API: 073-06477

Operator: JWC OPERATING LLC

Inspection Date: 5/17/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06477 | Date: 5/17/2022

## Inspection Photos



**Photo 1.** Facing east along the access road. It appears stormwater pool on the road in this area causing vehicles to widen the road. This area needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06477 | Date: 5/17/2022

## Inspection Photos



**Photo 2.** Facing south along the access roads.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06477 | Date: 5/17/2022

## Inspection Photos



**Photo 3.** There is another unnecessary access road being used to the battery. Vehicle shall not travel outside original access road boundary causing additional disturbance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06477 | Date: 5/17/2022

## Inspection Photos



**Photo 4.** Facing northwest toward the tank battery. The tank labels do not reflect current operator.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06477 | Date: 5/17/2022

## Inspection Photos



**Photo 5.** The signs at the battery do not reflect the current operator.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06477 | Date: 5/17/2022

## Inspection Photos



**Photo 6.** Facing southwest toward the well site. There is no posted well sign.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06477 | Date: 5/17/2022