

# Inspection Photos

API: 073-06379

Operator: NIGHTHAWK PRODUCTION LLC

Inspection Date: 5/17/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 073-06379 | Date: 5/17/2022

## Inspection Photos



**Photo 1.** Facing east toward the fenced location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06379 | Date: 5/17/2022



## Inspection Photos



**Photo 2.** Center of the location facing north.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06379 | Date: 5/17/2022



## Inspection Photos



**Photo 3.** Center of the location facing west.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06379 | Date: 5/17/2022



## Inspection Photos



**Photo 4.** Center of the location facing south.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06379 | Date: 5/17/2022



## Inspection Photos



**Photo 5.** Center of the location facing east.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06379 | Date: 5/17/2022

## Inspection Photos



**Photo 6.** The fence at the location is in disrepair.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06379 | Date: 5/17/2022