

**Inspection Photos**  
**Location Name: Leone Hosmer 4-11**  
**Location ID: 320357**



**Photo #1 Crude tank and produced water tank.**



**Photo #2 well sign in crude tank is faded and illegible.**

**Inspection Photos**  
**Location Name: Leone Hosmer 4-11**  
**Location ID: 320357**



**Photo #3 base of the berm thinning and causing a gap under the tanks.**



**Photo #4 base of the berm thinning and causing a gap under the tanks.**



**Inspection Photos**  
**Location Name: Leone Hosmer 4-11**  
**Location ID: 320357**



**Photo #5 no bull plug in in load-off line**



May 13, 2022 at 9:46:07 AM  
N 39° 54' 15", W 104° 33' 26"  
139° S  
Adams County Inspection

**Photo #6 thief hatch left open.**

**Inspection Photos**  
**Location Name: Leone Hosmer 4-11**  
**Location ID: 320357**




**Photo #7 wildlife netting has fallen in to open top tank.**



**Photo #8 Separator.**

**Inspection Photos**  
**Location Name: Leone Hosmer 4-11**  
**Location ID: 320357**



**Photo #9 Pump jack.**