

Inspection Photos

May 17, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 428570

Location Name: Simoes /31-30

Inspection Document #: 702800234

Moffat County, CO

Lot 6 Section 30 T6N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Simoes /31-30
Location ID: 428570



Photo 1. Photo taken from the north of the Location shows an overview of the Location. Final reclamation activities have been initiated. A dozer can be seen in the background replacing topsoil before decompacting the Location.



Photo 2. Refer to Photo 1 comment.

Inspection Photos
Location Name: Simoes /31-30
Location ID: 428570



Photo 3. Photo taken from the north of the Location shows highly compacted soils which were very difficult to penetrate with a shovel. Decompaction had not been performed.



Photo 4. Refer to Photo 3 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800234