

Inspection Photos

Operator: Monument Gas Marketing Inc. (59925)

Lease: Gladys Cotrell Trust #2

Facility ID/API, 285920 / 05-017-07641



1. Lease sign




2. Meter Sheds

Inspection Photos


Operator: Monument Gas Marketing Inc. (59925)

Lease: Gladys Cotrell Trust #2

Facility ID/API, 285920 / 05-017-07641



3. Tank Battery



4. Wellhead equipment




Inspection Photos

Operator: Monument Gas Marketing Inc. (59925)

Lease: Gladys Cotrell Trust #2

Facility ID/API, 285920 / 05-017-07641




5. Inadequate Berms



6. Inadequate Berms


Inspection Photos
Operator: Monument Gas Marketing Inc. (59925)
Lease: Gladys Cotrell Trust #2
Facility ID/API, 285920 / 05-017-07641




7. Gas supply line from wellhead scrubber to engine scrubber.

8. Casing gas directed to scrubber.

Inspection Photos
Operator: Monument Gas Marketing Inc. (59925)
Lease: Gladys Cotrell Trust #2
Facility ID/API, 285920 / 05-017-07641



9. Casing gas to wellhead scrubber



10. Casing gas from wellhead scrubber to engine scrubber.