

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403060105

Date Received:

05/26/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10634

Name of Operator: P O & G OPERATING LLC

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Charlotte Nash

713-244-0779

regulatory@pogresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693600212

Inspection Date: 03/18/2020

FIR Submit Date: 03/19/2020

FIR Status: _____

Inspected Operator Information:

Company Name: P O & G OPERATING LLC

Company Number: 10634

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 324942

Location Name: BEESON-610S45W Number: 21NENW County: KIT CARSON

Qtrqr: NENW Sec: 21 Twp: 10S Range: 45W Meridian: 6

Latitude: 39.172180 Longitude: -102.439110

FACILITY - API Number: 05-063-00 Facility ID: 213698

Facility Name: BEESON Number: 3-21

Qtrqr: NENW Sec: 21 Twp: 10S Range: 45W Meridian: 6

Latitude: 39.172180 Longitude: -102.439110

CORRECTIVE ACTIONS:

1 CA# 137305

Corrective Action: 604.c.(2).B.T., Well site cleared. Within ninety (90) days after a well is plugged and abandoned, the well site shall be cleared of all non-essential equipment, trash, and debris. Remove equipment and reclaim location.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 03/01/2022

Operator Comment: Location is ready for final re-inspection of P&A remediation

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Final Inspection requested

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Charlotte Nash

Signed:

Title: Prod & Regulatory Analyst

Date: 5/26/2022 7:45:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403060110	Inspection Report
-----------	-------------------

Total Attach: 1 Files