

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 1 – Weeds in Interim Reclamation Area



Photo 2 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 3 – Weeds in the Interim Reclamation Area



Photo 4 – Weeds in the Interim Reclamation Area

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 5 – Weeds in the Interim Reclamation Area



Photo 6 – Weeds in the Interim Reclamation Area

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730




Photo 7 – Wellhead



Photo 8 – Weeds in the Interim Reclamation Area

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 9 – Separators



Photo 10 – ECDs



Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Colorado Oil and Gas Conservation Commission
40.6843, -104.12194, 4884.8ft, 320°
05/25/2022 12:23:25



Colorado Oil and Gas Conservation Commission
40.68431, -104.12194, 4884.5ft, 135°
05/25/2022 12:23:28

Photo 11 – Tank Battery Sign

Photo 12 – Tank Battery



Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 13 – Risers Marked



Photo 14 – Compressor and Gas Meter Houses

