

# CAERUS PICEANCE LLC – 10456

API# 05-045-13367 N.PARACHUTE #WF09D M14 596

API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Inspection Date : 5/24/2022



API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Injection wellhead missing sign.

Temporarily Abandoned.

API# 05-045-13367 N.PARACHUTE #WF09D M14 596

Injection wellhead with sign.

Temporarily Abandoned



Tank battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Doc # 693804665



**CAERUS PICEANCE LLC – 10456**

**API# 05-045-13367 N.PARACHUTE #WF09D M14 596**

**API# 05-045-13404 N.PARACHUTE #WF10D M14 596**

**Inspection Date : 5/24/2022**



**Pump housing**



**Separator**