

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWSW

Location ID: 334788



Photo #6781 from entrance to location.



Photo #6782 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWSW

Location ID: 334788



Photo #6783 from entrance to location.



Photo #6784 Loadline open ended.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWSW

Location ID: 334788



Photo #6783 from entrance to location.



Photo #6786 Vent pipe on tank open ended.