

TEP
Anchando
Location # 335119



location



location



TEP
Anchando
Location # 335119



location



location



TEP
Anchando
Location # 335119



Tank not labeled



Tank not labeled

TEP
Anchando
Location # 335119



Tank not labeled



Stored equipment (ECD)



Photo taken from the northern production area of the Location facing east shows signs of lack of stabilization BMPs in some areas (rutting is present). Photo taken by reclamation inspector.

TEP
Anchando
Location # 335119



Recent inspection showing C/A has not been completed.



Previous inspection photo taken from the center of the Location facing east shows signs of lack of stabilization BMPs in some areas (rutting is present). Photo taken by reclamation inspector.

TEP
Anchando
Location # 335119



Recent inspection showing C/A has not been completed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources