

Inspection Photos
Location Name: SHABLE USX AB /11-09P
Location #: 416209




Photo #1

Shable USX AB 11-09P (05-123-31319) Wellsite
Temporarily Abandoned | TA



Photo #2

Shable USX AB 11-09P, 11-16P Battery site
Abandoned: ALL Equipment Removed
Formerly served:
Shable USX AB 11-08P ; Plugged & Abandoned | PA