

Inspection Photos

API: 071-07564

Operator: OGRIS OPERATING LLC

Inspection Date: 6/1/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07564 | Date: 6/1/2022

Inspection Photos



Photo 1. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07564 | Date: 6/1/2022

Inspection Photos



Photo 2. There is oil in the engine skid that has spilled over that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07564 | Date: 6/1/2022