

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 28NWN
Location # 315379



LASSO OIL & GAS LLC
CONTINENTAL-63S100W 28NWN
Location # 315379



No sign at well head. Local EMS or 911 not posted.



Bradenhead access is not present.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 28NWN
Location # 315379



Gas leak from check valve between separator and meter house.



Gas leak from check valve between separator and meter house.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 28NWN
Location # 315379



Most recent meter calibration in June 2019.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 28NWNE
Location # 315379



Ditch not maintained from lease road and thru location. Storm water runs into pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 28NWN
Location # 315379



Wall of pit has erosion damage.



Wall of pit has erosion damage.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 28NWE
Location # 315379



Fiberglass tank is full of fluid

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 28NWN
Location # 315379



Corner of fence is falling.