

Inspection Photos

Location Name: Dillard USX AB /05-99HZ

Location #: 415930



Photo #1

Dillard USX AB 05-99HZ (05-123-31254) Wellsite

Shut-In | SI

Well appears intact



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources