

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 1 – Signs at Entrance

Photo 2 – Wellheads

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 3 – Gas Lift Injection Meter Shed



Photo 4 – Separators



Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 5 – Separators



Photo 6 – Tank Battery

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 7 – LACTs



Photo 8 – Tank Battery and VRTs

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 9 – ECDs



Photo 10 – VRUs



Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 11 – Gas Meter Sheds



Photo 12 – Compressors

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475




Photo 13 – Wildlife Netting in disrepair and debris



Photo 14 – Debris and Wildlife Netting in disrepair



Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 15 – Wildlife Netting in disrepair and debris



Photo 16 – Unused Tank and Stand