

# Inspection Photos

May 25, 2022

Operator: Chevron USA Inc - #16700

Location ID: 398843

Location Name: Wilson Creek Unit-63N94W /35SESW

Inspection Document #: 702800280

Rio Blanco County, CO

SESW Section 35 T3N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /35SESW

Location ID: 398843



**Photo 1.** Photo taken from the east of the Location shows an overview of the northern portion of the Location. The area appears to have been seeded with native perennial grasses.



**Photo 2.** Photo taken from the north of the Location shows the vegetation community consists of native perennial grasses. Undesirable and noxious weeds are also present.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800280



## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /35SESW

Location ID: 398843



**Photo 3.** Photo taken from the south of the Location shows the vegetation community in this area is dominated by undesirable and noxious weeds.



**Photo 4.** Photo taken adjacent to the Location, to the north shows reference area vegetation.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800280