

Inspection Photos

Location Name: Hubbs #2 and tank battery

Location ID: 306993



IMG 01
Well sign



IMG 02
Site Overview



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



IMG 03
Impacted material



IMG 04
Combustor



IMG 05

Tank battery sign



IMG 06

Berms are affected by burrows



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources