

**LASSO OIL & GAS LLC**  
**CONTINENTAL 63S100W 28NWNE**  
**Location # 315379**



**Bradenhead access is not present.**  
**No sign at well head. Local EMS or 911 not posted.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**LASSO OIL & GAS LLC**  
**CONTINENTAL 63S100W 28NWNE**  
**Location # 315379**



**Gas leak from check valve between separator and meter house**



**Gas leak from check valve between separator and meter house**



**LASSO OIL & GAS LLC**  
**CONTINENTAL 63S100W 28NWE**  
**Location # 315379**



**Most recent meter calibration in June 2019.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**LASSO OIL & GAS LLC**  
**CONTINENTAL 63S100W 28NWNE**  
**Location # 315379**



**Ditch not maintained from lease road and thru location. Storm water runs into pit.**



**LASSO OIL & GAS LLC**  
**CONTINENTAL 63S100W 28NWN**  
**Location # 315379**



**Wall of pit has erosion damage.**



**Wall of pit has erosion damage.**



**LASSO OIL & GAS LLC**  
**CONTINENTAL 63S100W 28NWNE**  
**Location # 315379**



**Fiberglass tank is full of fluid**



**Fiberglass tank is full of fluid**