

# Final Reclamation Inspection

May 11th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 328048

Inspection Document #: 701900368

NENE Section 7 T3N R64W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dechant 7-11  
Location ID: 328048



**Photo 1.** 2022 aerial imagery of the well pad and reference area. Note: The tank battery (highlighted in blue) remains to service the TA well API # 123-15477 not pictured to the south.



Inspection Photos  
Location Name: Dechant 7-11  
Location ID: 328048



**Photo 2.** Overview photo of the well pad taken at ground level from the eastern edge looking west. Note: well pad does not appear consistent with reference area (see photo 3).



Inspection Photos  
Location Name: Dechant 7-11  
Location ID: 328048



**Photo 3.** Reference area to the north of the well pad.