

# Final Reclamation Inspection

May 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 307213

Inspection Document #: 701900385

NESW Section 25 T5N R68W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**


Department of Natural Resources

Inspection Photos  
Location Name: Ryan 23-25U  
Location ID: 307213



**Photo 1.** 2021 aerial imagery of the well pad. Tank battery highlighted in blue is associated with the Ryan 25-BU well (API # 063-06334).

Inspection Photos  
Location Name: Ryan 23-25U  
Location ID: 307213



**Photo 2.** Overview photo of the well taken with a drone from the eastern edge looking west.



Inspection Photos  
Location Name: Ryan 23-25U  
Location ID: 307213



**Photo 3.** Close-up photo of the well pad taken with a drone from the eastern edge looking west. Note: well pad disturbance shows stunted crop growth.