

Inspection Photos and Issue Report

6/07/2022

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312537

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312537



Photo 1: Photos 1-2 provide an overview of the Location facing west, northwest, northeast to east. Location has not been reclaimed in accordance with 1004 requirements; shrub establishment evident, however large majority of the Location is bare soils, or Undesirable and Noxious Plant species such as Jointed Goatgrass, Field Bindweed, Annual wheatgrass and cheatgrass. Pit on Location also has not been closed/reclaimed; access road has not been reclaimed; surface owner appears to be using area as a storage area, and the pit as a dumpsite; no variance to waive reclamation requirements of the Location or pit has been approved for this site.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312537



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312537



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312537



Photo 4: Well marker on Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312537



Photo 5: Photo shows pit on the Location has not been closed/reclaimed. Surface owner appears to be using site as a dump and storage area.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312537



Photo 6: Photo example of Undesirable and Noxious plant species evident throughout the Location. Photo specifically shows Jointed Goatgrass on the Location. Other Undesirable and Noxious Plant Species include Field Bindweed, Annual wheatgrass and Cheatgrass.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312537



Photo 7: Photos example showing access road to the Location has not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312537



Photo 8: Photos example showing culvert and cattle guard remaining; Oil and Gas access road has not been reclaimed.

Inspection Photos



Photo 9: 2016 Google Earth Aerial imagery. Photo shows Location (yellow polygon) and access road (red line) requiring reclamation pursuant to 1004 rules.

