

Inspection Photos

API: 055-06189

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/7/2022

Inspection Photos



Photo 1. Facing south along the former access road. The access road consists of noxious weeds; Red stem filaree.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/7/2022

Inspection Photos



Photo 2. Facing southeast toward the location. It appears previous weed control was performed due to bare ground over most of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/7/2022

Inspection Photos



Photo 3. There appeared to be drill rows from reseeded areas however there is no seedling germination.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/7/2022

Inspection Photos



Photo 4. Facing west toward the location. The location will need to be reseeded and any remaining noxious weeds controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/7/2022